Ref #	Hits	Search Query	DBs	Default Operator	·Plurals	Time Stamp
S82	114	"29"/\$.ccls. and (power near2 control) and (curve or plot or graph)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:37
S97	116	(700/212).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 14:59
S11 1	578	(156/580.1).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 15:51
S11 2	427	(156/580.2).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 15:51
S11 6	0	(power near10 correction) and (curve or plot or graph) and (welding or weld) and ("29"/\$.ccls. or "156"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 14:12
S11 7	116	(700/212).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23
S11 8	6	((156/64).CCLS.) and (sonotrode)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 13:41
S11 9	46	((156/64).CCLS.) and (ultrasonic and horn)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23

S12 0	6	(((156/64).CCLS.) ((156/73.1). CCLS.) ((156/73.4).CCLS.) ((156/73.3).CCLS.) ((156/73.2). CCLS.) ((156/73.5).CCLS.) ((156/73.6).CCLS.) ((156/358). CCLS.) ((156/359).CCLS.) ((156/360).CCLS.) ((156/366).CCLS.)) ((156/367).CCLS.) ((156/378). CCLS.) ((156/379).CCLS.) ((156/580.1).CCLS.) ((156/580.2). CCLS.)) and (weld\$ near3 parameter) and (curve or plot or graph) and (ultrasonic or ultrasound or sonotrode)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23	
S12 1	28	"29"/\$.ccls. and (power near2 control) and (curve or plot or graph) and (welding or weld)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23	
S12 2	45	"700"/\$.ccls. and (power near2 control) and (curve or plot or graph) and (welding or weld)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23	
S12 3	9	(error near10 correction) and (curve or plot or graph) and (welding or weld) and ("29"/\$.ccls. or "156"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23	
S12 4	87	(power near10 adjust\$5) and (curve or plot or graph) and (welding or weld) and ("29"/\$.ccls. or "156"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23	
S12 5	69	(ultrasound or ultrasonic or friction) and (grewell.in. or frantz.in.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23	
S12 6	12	"700"/\$.ccls. and (energy near2 input) and (curve or plot or graph) and (welding or weld)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23	
S12 7	26	"156"/\$.ccls. and (energy near2 input) and (curve or plot or graph) and (welding or weld)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23	

S12 8	271	(error near10 correction) and (curve or plot or graph) and (welding or weld)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23
S12 9	1362	(156/64).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	OFF	2005/03/16 12:23
S13 0	70	(closed near4 loop) and (curve or plot or graph) and (welding or weld) and ("29"/\$.ccls. or "156"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 12:23
S13 1	71	(close\$1 near5 loop) and (curve or plot or graph) and (welding or weld) and ("29"/\$.ccls. or "156"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 14:16
S13 2	28	(close\$1 near5 loop) and (curve or plot or graph) and (ultrasonic and bond\$4) and ("29"/\$.ccls. or "156"/\$.ccls.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 15:13
S13 3	. 4	(("5435863") or ("5658408") or ("5855706") or ("5846377")).PN.	USPAT	OR	OFF	2005/03/16 15:13
S13 4	1501	(156/73.1).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S13 5	199	(156/73.4).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S13 6	156	(156/73.3).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S13 7	207	(156/73.2).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24

S13 8	686	(156/73.5).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S13 9	238	(156/73.6).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S14 0	414	(156/358).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S14 1	507	(156/359).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S14 2	~ 271	(156/360).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S14 3	299	(156/366).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S14 4	282	(156/367).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
\$14 5	784	(156/378).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24

S14 6	225	(156/379).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:24
S14 7	5321	((156/64).CCLS.) ((156/73.1).CCLS.) ((156/73.4).CCLS.) ((156/73.3). CCLS.) ((156/73.5).CCLS.) ((156/73.5).CCLS.) ((156/73.6). CCLS.) ((156/358).CCLS.) ((156/359).CCLS.) ((156/360).CCLS.) ((156/366).CCLS.) ((156/367). CCLS.) ((156/378).CCLS.) ((156/379).CCLS.) ((156/580.1). CCLS.) ((156/580.2).CCLS.)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:25
S14 8	17	"702"/\$.ccls. and (power near2 control) and (curve or plot or graph) and (welding or weld)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/03/16 17:25